	SURVEY NUMBER:
	2 Tower Terrace
	NEGATIVE FILE NUMBER: 77-A-213
OF VERMONT	UTM REFERENCES:
Division for Historic Preservation	Zone/Easting/Northing
Montpelier, VT 05602	Zone, Lasting, Northing
HICHORIC CIMES C CONTINUES CHRIST	U.S.G.S. QUAD. MAP:
HISTORIC SITES & STRUCTURES SURVEY	U.S.G.S. QUAD. MAP:
Individual Structure Survey Form	PRESENT FORMAL NAME:
	RESENT FORMAL NAME:
COUNTY: Chittenden	ORIGINAL FORMAL NAME:
TOWN: Burlington	carriage house for 301 So. millard
LOCATION:	PRESENT USE: dwelling
	ORIGINAL USE:
	ARCHITECT/ENGINEER:
COMMON NAME:	
	BUILDER/CONTRACTOR:
FUNCTIONAL TYPE: carriage house	
OWNER: Virginia Davis	PHYSICAL CONDITION OF STRUCTURE:
ADDRESS: 2 Tower Terrace	Excellent Good
	Fair Poor D
ACCESSIBILITY TO PUBLIC:	THEME:
Yes No Restricted	STYLE: shingle
LEVEL OF SIGNIFICANCE:	HDATE BUILT:
Local State National	1895
GENERAL DESCRIPTION:	
Structural System	
	☐ Concrete ☐ Concrete Block ■
2. Wall Structure	Concrete D concrete block
a. Wood Frame: Post & Bea	m [] Palloon
	Brick Stone Concrete
Concrete Block	Bilck [] Stolle [] Colletete []
	a Othora
c. Iron d. Steel d	e. Other: ] Board & Batten [] Wood Shingle
	tucco
	Veneer ☐ Stone Veneer ☐
Bonding Pattern:	Other:
4. Roof Structure	desil Comments C
	] Steel [ Concrete [
b. Other:	
	Wood Shingle Asphalt Shingle
	☐ Rolled ☐ Tile ☐ Other:
6. Engineering Structure:	
7. Other:	
Appendages: Porches Towers	
Sheds Ells Wings Oth	ner:
	l 🔲 Flat 🗍 Mansard 🗍 Gambrel 🗆
Jerkinhead  Saw Tooth  With	
With Parapet   With False Front	:   Other:
Number of Stories: 1 1/2	
Number of Bays: 2 x 3	Entrance Location: on south wall
Approximate Dimensions:	
THREAT TO STRUCTURE:	LOCAL ATTITUDES:
No Threat ☐ Zoning ☐ Roads ☐	Positive   Negative
Development   Deterioration	Mixed Other:
Alteration  Other:	

RIPTION: tion. 2 story round ped roof dormer. ti-pane windows of carriage entrances. ght roof screens.	Large shed in facade 2nd with ellipti- Converted
tion. 2 story roupped roof dormer.  ti-pane windows of carriage entrance.  ght roof screens.	Large shed in facade 2nd with ellipti- Converted
ilt in 1895 by Jo	
ilt in 1895 by Jo	
ilt in 1895 by Jo	
The carriage ho its shingle clad	use monmogenta
4	
DING ENVIRONME Land	nd   crcial  ustrial
	DING ENVIRONME Land  Woodla ered Buildings ately Built Up ly Built Up [] lential  Comm cultural Ind :

